

Er. J.VARA PRASAD

BE, PGDCM, C. ENG. (i), FIV

MICA, MIE, M.I.STRUCT.E

CHARTERED ENGINEER,

APPROVED ENGINEER

TO ISSUE BUILDING STRUCTURAL STABILITY CERTIFICATE

35, Jai Hind Flats

Anna Nagar (West),

Chennai – 600 040.

Email : jvprasaad@gmail.com

CELL : 99623 99199 ,

Office : 99623 54541

STATEMENT ACCOMPANYING FORM 'A' STRUCTURAL STABILITY

1. Name of the School : **ELITE PUBLIC SCHOOL (CBSE)**
2. Location street No. Ward No : **Survey No.394/1B,1C1,1D & E, (As informed/Reported)**
Sirupuzhalpettai Part -1 Village,
Name of place, (i.e.) corporation **Gummidipoondi Taluk,**
Municipality /Panchayath / **Tiruvallur District .**
3. Year of construction : **U Shape Building**
: **RCC : GF & FF- 2010 – About 15 years**
4. Cost of Construction : **About Rs.30.00 Lacs Each Floor**
5. Purpose for which the building is : **For Conducting School Classes**
being used or proposed to be used
6. Purpose for which the building has : **For Conducting School Classes**
hitherto been used
7. Details of construction of the building
(particulars) of the foundation, soil
specification of the various parts as under
 - a. Foundation : **RCC Isolated footings, grade beam,**
 - b. Basement : **Brick Work in Cm, Plinth Beam**
 - c. Superstructure : **RCC Columns & Beam, Brick work in CM**
 - d. Floor &Roof ,are to be given : **Roof – RCC,**
Flooring : Cement Mortar .
8. Period for which license is required : **From 01.06.2025 to 31.05.2028**
FOR THREE YEARS ONLY
9. No. of persons to be accommodated : **About 1500 Pupils.**
(One Thousand Five Hundred Pupils Only)

Place : Chennai

Date : 28.05.2025

J.VARA PRASAD,
PGDCM.,C.Eng.FIV.,MIE.,MICA.,M.I.Struct.E.,
Chartered Engineer,
Approved Engineer in Collector's Panel,
Competent Person to Issue Stability Certificate
No. 283/35, 2nd Floor, Jai Hind Flats,
Belly Area, NR, Chinmaya School,
Anna Nagar West, Chennai - 600 040.
Cell: 99623 99199, 94433 79627
Office: 99623 54541, 944-2626 0799




FORM – B
STATEMENT TO ACCOMPANY THE REPORT OF STRUCTURAL SOUNDNESS

Location of the Building door No. Street Name & Name of the Place.	Age of the Building	Value of the Buildings	No of Storeys	Short Description of Structure, steel RCC Framed or load bearing Masonry.
ELITE PUBLIC SCHOOL CBSE	GF & FF -2010	About Rs.30.00	RCC : GF,FF	RCC Isolated Footing
Survey No.394/1B,1C1,1D & E	About 12 Years	Lacs Each Floor		Brick work in Cm, Plinth Beam
Sirupuzhalpettai Part-1 Village,				RCC Columns & Beam,Brick work in Cm
Gummidipoondi Taluk, Tiruvallur District				RCC: Roof, Flooring : Cement Mortar

Purpose for which The building is To be used	period for which the license is required	No. of Persons Accommodated.	Remarks
For Conducting School Classes FOR THREE YEARS ONLY (One Thousand Five Hundred Pupils Only) (Subject to Remarks)	01.06.2025 to 31.05.2028	About 1500 Pupils	The Building is Structurally Sound
This Report does not include any Eventualities caused by Natural Calamities. <u>We here by advise that the Periodical Repairs and Renovations Shall be carried out to the Entire Building Block regularly.</u> Further Necessary fire fighting equipment's should be kept in the premises and should be trained for operation. If any fire accident / Mishap occurs we are not held responsible. <u>Structural Alteration / Deviation Should Not be Carried out to a part / whole Building without Prior Permission from the Competent Authority.</u> If any additional construction is made subsequently structural soundness has to be obtained. Emergency Exit to be provided as per norms. All electrical points, wiring / Gadgets has to be checked properly and to be maintained periodically. All Panel Boards, Main Switches/Cables, has to be kept in Lock and Key position. Electrical Conduits/ Cables should not be loosely Run on the open ground/ flooring it has to be put in Cable Trenches covered by slabs with at most safety and precaution. Stagnation of rain Water in Open Terrace or in any other Part should be drained through proper Outlets. Weathering coarse for terrace and Water Proofing / Treatment has to be done to the Roof and to be periodically maintained. Any Construction/ Repairs/ Alteration work should not be carried out during School working hours. If Any Cracks in walls and in Ceiling is found it has to be rectified and Re- Plastered. Trees adjoining the Buildings has to be Pruned and the branches has to be Trimmed. The Management is Strictly advised to stop the Classes during heavy , Gale, Floods ,Rain, Cyclone and Wind. All Necessary safety standards has to be Strictly adhered / Followed. Emergency Exit Doors/ staircase has to be Provided as per norms. Open Terrace, Corridor and Staircase must be barred with safety Grills . Approved Plan for the Building is not produced. This Certificate is issued based on physical inspection of the structure and actual available in the premises on the date of inspection. This Certificate Covers RCC Roof Permanent Structure alone. AC Sheet / Metal sheet roof shed, Entrance arch, Compound wall, semi/ Non permanent structure is not Considered in this Certificate. Septic tank cleaning guidelines has to be followed according to pollution control board norms. If any deviation/ violations/ Lapse in safety norms are found at a later period after issue of this Report / License The Engineer is not held responsible and this Report gets Invalid and automatically gets cancelled. Further this Report covers the above said Mentioned Building Block only. Legal Aspects such as Title , Ownership, Encumbrances if any were not considered and as it is not within this scope of this report.			

Place : Chennai

Dated : 28.05.2025


J. V. PRASAD,
 Chartered Engineer,
 Approved Engineer in Collector's Panel,
 Competent Person to Issue Stability Certificate
 No. 293/35, 2nd Floor, Jai Hind Flats,
 Bally Area, NR, Chinnaya School,
 Anna Nagar West, Chennai- 600 040.
 Phone : 98403 79527
 Email : jvprasad@rediffmail.com



FORM – C

Form of Report of structural soundness under sub-section (4) of section 4 of
The Tamil Nadu public building (licensing) Act 1965 (Tamil Nadu act 1 of 1965) Referred to in rule 4 of the
Tamil Nadu public (Licensing) Rules, 1966.

We have inspected the building mentioned in the statement and furnish below its salient technical
features:

1. Foundation :

- a. Depth below ground level : About 1.52 Mts.
- b. Nature of soil met with at
foundation level. : Red Soil
- c. Pressure at foundation : --
- d. Probable safe bearing capacity of
The soil strata met with at foundation : About 17 Mts. / Sq. M


2. Superstructure : Brick work in Cm

- a. Minimum stress in the most :
Critical section of : Within Limits
Masonry and concrete
- b. Nature of masonry and concrete : Brick Masonry
And its safe permissible stress : Within Limits

We are of the Opinion that the building is structurally sound. A license can be granted for the period
from 01.06.2025 to 31.05.2028 (FOR THREE YEARS ONLY)

Place: Chennai.

Date : 28.05.2025


J. VARA PRASAD,
PGDCM., C.Eng., FIV., MIE., MICA., M.I. Struct E.,
Chartered Engineer,
Approved Engineer in Collector's Panel,
Competent Person to Issue Stability Certificate
No. 283/35, 2nd Floor, Jal Hind Flats,
Belly Area, NR, Chinmaya School,
Anna Nagar West, Chennai - 600 040.
Phone: 9840370627
Mobile: 9840370627



Er. J.VARA PRASAD

BE,DCM, C. ENG. (i), FIV

AMIE, M.I.STRUCT.E

CHARTERED ENGINEER,

APPROVED ENGINEER

TO ISSUE BUILDING STRUCTURAL STABILITY CERTIFICATE

35, Jai Hind Flats

Anna Nagar (West),

Chennai – 600 040.

Email : jvprasaad@gmail.com

CELL : 99623 99199,

Office : 99623 54541

ANNEXURE TO "STATEMENT ACCOMPANYING FORM – A"

We have inspected the School Building premises of **ELITE PUBLIC SCHOOL (CBSE)** Located at Survey No.394/1B,1C1,1D & E, (As informed/Reported) , Sirupuzhalpettai Part -1 Village 1, The following Building is of **" U SHAPE BLOCK"** : RCC : GF & FF- 2010 – About 15 years is available.

This Report does not include any other Buildings/ Blocks or Structures Such as Compound wall, Entrance arch, Metal sheet shed, Semi/ Non-permanent Structures either in GF or in any other floors etc., We here by advise That the Periodical Repairs and Renovations Shall be carried out to the Entire Building Block regularly.

Further Necessary firefighting equipment's should be kept in the premises and should be trained for operation. If any fire accident / Mishap occurs we are not held responsible. Emergency exit to be provided as per norms. Structural Alteration / Deviation Should Not be carried out to any of the block for Whole Building Or any Part of Building Without Prior Permission from the Competent Authority. This Certificate is issued based on physical inspection of the structure and actual available in the premises on the date of inspection. All Electrical points, wiring / Gadgets has to be checked properly and to be maintained regularly. Periodic water proofing treatment is to be done as per Standards. Weathering Coarse for Terrace and Water Proofing/ Treatment has to be done to the Roof and to be Periodically Maintained. Any Construction / Repairs/Maintenance Alteration Work Should not be Carried out during School Working Hours. safety Grills has to be provided in FF Corridor. Open terrace Grill gate has to be kept in lock and key . Head room side panel walls dampness has to be rectified. A part of South West portion of Building roof ceiling has to be repaired. **This Report does not cover any Structure / Partly completed Structure or building under construction. Any Further additional construction either in G.F, FF or in any other Floors / Blocks the necessary approvals / structural design / Soundness has to be Subsequently obtained.** Electrical Conduits/ Cables should not be loosely Run on the open ground/ flooring it has to be put in Cable Trenches covered by slabs with at most safety and precaution. The UG sump, manholes, OHT, Inspection Chamber Openings has to be Sealed with cover slab and with regard to Waste Disposal and Cleaning this necessary guidelines has to be obtained and followed according to Pollution control Board Norms. The entire premises should be kept in neat and clean position without any dumping of waste material and construction debris. **All Necessary safety Norms and standards has to be Strictly adhered/ Followed.** If any deviation/ violations/ Lapse in safety norms are found at a later period after issue of this Report / License The Engineer is not held responsible and this Report gets Invalid and automatically gets cancelled. Further this Report covers the above said RCC Roof Building alone only. AC Sheet / Metal sheet shed is not Considered in this Certificate. Legal Aspects such as Title, Ownership / Encumbrances if any were not considered and has its not within the scope of this certificate.


Place : Chennai

Date : 28.05.202


J.VARA PRASAD,
PDCM, C. ENG. (i), FIV
Chartered Engineer,
Approved Engineer in Collector's Panel,
Competent Person to Issue Stability Certificate
No. 283/35, 2nd Floor, Jai Hind Flats,
Belly Area, NR, Chinmaya School,
Anna Nagar West, Chennai - 600 040.
Cell : 99623 99199, 94433 79627
Office : 99623 54541



PHOTOCOPIES



PEDRO L. GARCIA, M.C.E., M.I. Struct E.,
Chartered Engineer,
Approved Engineer in Collector's Panel,
Competent Person to Issue Stability Certificate
No. 293/33, 2nd Floor, Jai Hind Flats,
Bally Area, D.R. Chinnaya School,
Aurore Road West, Chennai - 600 040.
Mobile No. 9443379657
Fax No. 8426 8789



ASAD,
CA., M.I. Struct E.,
near,
Director's Panel,
Habitat Certificate
at Hind Gats,
aya School,
Wash & Wash - 600 040.
94433 73017
94433 73017